Capsule Summary SM-823 Wallace House Compton vicinity Private

circa 1943

Constructed circa 1943, the Wallace house reveals how architectural details were slow to change even in the mid-twentieth century. Located on the west side of Bay Side Road in the rural crossroads community of Compton, Maryland, the Wallace House is a two story, three bay, frame residence with a gable roof. Following the architectural traditions of the late-nineteenth and early twentieth centuries, the dwelling illustrates how porch decorations remained relatively unchanged. The east side porch retains turned posts, scroll sawn brackets as well as a balustrade and rail. Due to the rather common occurrence of this building type across the county, no further investigation is necessary.

Inventory No. SM-823

Maryland Historical Trust Maryland Inventory of Historic Properties Form

1. Name of F	Property	(indicate preferred	name)					
historic						·		
other	Wallace House							
2. Location								
street and number	22203 Bay Sid	le Road				_	_ not	for publication
city, town	Compton					_	_ vici	nity
county	St. Mary's							
3. Owner of	Property	(give names and mailin	ng address	ses of all o	wners)			
name	Robert and Joy	vce Wallace						
street and number	PO Box 134				telep	hone	N/a	
city, town	Compton		state	Md	zip c	ode	2062	7-0134
4. Location of								
	·	St. Mary's County Courtho	use		tax map and			
city, town	Leonardtown				liber	DBK	184	folio 70
Contrib Contrib Determ Record Historic	outing Resource outing Resource nined Eligible for nined Ineligible fi ded by HABS/HA	ort or Research Report at Mh	and Regis ylarıd Reg					
6. Classifica	tion							
Categorydistrict _x_building(s)structuresiteobject	Ownershippublicx_privateboth	Current Function agriculturecommerce/tradedefensex_domesticeducationfunerarygovernmenthealth careindustry	resotrawourva	ndscape creation/co ligion ocial ansportatio ork in prog aknown acant/not in	Coulture		Contri	t Noncontributing buildings sites structures objects Total ibuting Resources in the Inventory

7. Description	<u> </u>	Inventory No. SM-823
Condition		
excellent x good fair	deteriorated ruins altered	

Prepare both a one paragraph summary and a comprehensive description of the resource and its various elements as it exists today.

Situated on a 2.77 acre parcel on the west side of Bay Side Road in the rural crossroads community of Compton, Maryland is the Wallace House. The dwelling is oriented on an east/west axis and is approached via a dirt drive that extends to the west of the main road. Positioned in the middle of the lot, the dwelling is surrounded by a mowed lawn and well manicured landscaping and mature deciduous trees. The property is bounded to the north and south by residential parcels, to the west by a wooded lot, and to the east by the road.

The Wallace House, constructed circa 1943, is a two story, side passage, three bay, frame dwelling with a gable roof. Sheathed with faux weatherboard, the exterior walls are slightly shaded by an enclosed overhanging eave. The gable roof is clad with asphalt shingles and is pierced by two interior brick chimney flues.

The primary or east elevation is pierced on the first floor by a door and two sets of paired, six-over-six, double-hung sash windows. Each pair of windows only features one pair of louvered shutters. All of these bays are shaded by a porch elegantly embellished by turned porch posts, scroll sawn brackets, and a balustrade and rail. Above the roof of the porch are three symmetrically placed six-over-six windows each with louvered shutters.

The south elevation is pierced on the first floor by a paired set of six-over-six windows and a single six-over-six window. The second floor is pierced by two six-over-six window. The attic story is lit by a window of unknown sash.

Other elevations were not investigated.

8. Signific	cance			Inventory No. SM-823
Period	Areas of Significance	Check and ju	ustify below	
1600-1699 1700-1799 1800-1899 <u>x</u> 1900-1999 2000-	agriculture archeology x architecture art commerce communications community planning conservation	 economics education engineering entertainment/ recreation ethnic heritage exploration/ settlement 	health/medicine industry invention landscape architecture law literature mantime history military	performing arts philosophy politics/government religion science social history transportation other:
Specific dates			Architect/Builder	
Construction of	lates			
Evaluation for:				
	_ National Register	M	laryland Register	x not evaluated

Prepare a one-paragraph summary statement of significance addressing applicable criteria, followed by a narrative discussion of the history of the resource and its context. (For compliance projects, complete evaluation on a DOE Form – see manual.)

Constructed circa 1943, the Wallace house reveals how architectural details were slow to change even in the mid-twentieth century. Located on the west side of Bay Side Road in the rural crossroads community of Compton, Maryland, the Wallace House is a two story, three bay, frame residence with a gable roof. Following the architectural traditions of the late-nineteenth and early twentieth centuries, the dwelling illustrates how porch decorations remained relatively unchanged. The east side porch retains turned posts, scroll sawn brackets as well as a balustrade and rail. Due to the rather common occurrence of this building type across the county, no further investigation is necessary.

9. Major Bibliographical References

Inventory No. SM-823

Hammett, Regina Combs. History of St. Mary's County, Maryland: 1634-1990. Ridge, Md: Self-published, 1994.

10. Geographical Data

Acreage of surveyed property	2.77 acres		
Acreage of historical setting	same		
Quadrangle name	Leonardtown	Quadrangle scale:	1:24 000

Verbal boundary description and justification

The property is bounded to the north and south by residential parcels, to the west by a wooded lot, and to the east by the road. A more specific description of the properties boundaries can be found in St. Mary's County Land Records Liber DBK 184, Folio 70.

11. Form Prepared by


name/title	Kirk E. Ranzetta, Historic Sites Surveyor		
organization	St. Mary's County Department of Planning & Zoning	date	August, 2000
street & number	22740 Washington Street	telephone	301-475-4662
city or town	Leonardtown	state	Maryland

The Maryland Inventory of Historic Properties was officially created by an Act of the Maryland Legislature to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 supplement.

The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

retum to:

Maryland Historical Trust DHCD/DHCP 100 Community Place Crownsville, MD 21032-2023 410-514-7600





511 -823 Wallace House $\mathcal{J} \neq n$ Looking W